



The State of Utah

Department of  
Natural Resources

Division of  
Oil, Gas & Mining

ROBERT L. MORGAN  
Executive Director

LOWELL P. BRAXTON  
Division Director

OLENE S. WALKER  
Governor

GAYLE F. McKEACHNIE  
Lieutenant Governor

**Representatives Present During the Inspection:**

Company	Guy Davis	Environmental Scientist
OGM	Steve Demczak	Environmental Scientist III

# Inspection Report

Permit Number:	C0150017
Inspection Type:	COMPLETE
Inspection Date:	Wednesday, August 29, 2007
Start Date/Time:	8/29/2007 10:00:00 AM
End Date/Time:	8/29/2007 2:00:00 PM
Last Inspection:	Monday, July 23, 2007

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 80's

InspectionID Report Number: 1390

Accepted by: dhaddock *OK*  
9/12/2007

Permitee: **PACIFICORP**

Operator: **ENERGY WEST MINING CO**

Site: **DES BEE DOVE MINE**

Address: **PO BOX 310, HUNTINGTON UT 84528**

County: **EMERY**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **RECLAIMED**

**Current Acreages**

154.86	<b>Total Permitted</b>
36.22	<b>Total Disturbed</b>
	<b>Phase I</b>
	<b>Phase II</b>
	<b>Phase III</b>

**Mineral Ownership**

- ☒ Federal  
☐ State  
☐ County  
☒ Fee  
☐ Other

**Types of Operations**

- ☒ Underground  
☐ Surface  
☐ Loadout  
☐ Processing  
☐ Reprocessing

**Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:**

Water monitoring activities at this site have been discontinued with the reclamation of the last UPDES outfall (the sediment pond discharge point).  
The 2006 Annual Report for the Des-Bee-Dove site was received at the DOGM on May 1, 2007. Review of the submitted information is pending.

Inspector's Signature: \_\_\_\_\_

*Steve Demczak*  
Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Date

Thursday, August 30, 2007

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801  
telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 [www.ogm.utah.gov](http://www.ogm.utah.gov)

**Utah!**  
Where ideas connect™

Permit Number: C0150017  
 Inspection Type: COMPLETE  
 Inspection Date: Wednesday, August 29, 2007

## Inspection Continuation Sheet

Page 2 of 3

### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**1. Permits, Change, Transfer, Renewal, Sale**

The permit will expire on August 20, 2010. The Division has granted a Phase III bond release for a small area being use for gas drilling.

**3. Topsoil**

All topsoil was used in reclamation.

**4.a Hydrologic Balance: Diversions**

The diversion were functioning as designed.

**4.b Hydrologic Balance: Sediment Ponds and Impoundments**

The reclaimed mine site has no sediment ponds.

**4.c Hydrologic Balance: Other Sediment Control Measures**

No sediment was noticed going off site.

**4.e Hydrologic Balance: Effluent Limitations**

No UPDES points at this reclaimed mine site.

**10. Slides and Other Damage**

I did not see any slides or damage during the inspection.

**12. Backfilling And Grading**

Backfilling and grading is completed.

**13. Revegetation**

The area has been seeded.

**21. Bonding and Insurance**

The insurance policy number is X0720A1A07. This policy will expire on August 28, 2008. The bonding amount is \$1,837,712.